## RECEIVED

Revised 10/09

CORRES. CONTROL INCOMING LTR NO.

## 200) GCT 15 A 9 110 STATE OF COLC

00956 RF03

Bill Owens, Governor Douglas H. Benevento, Executive Director

Dedicated to protecting and improving the health and environment of the people of Colorado

DUE DATE 4300 Cherry Creek Dr. S. ACTION Denver, Colorado 80246-1530

Phone (303) 692-2000 TDD Line (303) 691-7700

Located in Glendale, Colorado

http://www.cdphe.state.co.us

Laboratory and Radiation Services Division 8100 Lowry Blvd. Denver, Colorado 80230-6928

(303) 692-3090

Colorado Department of Public Health and Environment

DIST BERARDINI, J. H BOGNAR, E. S BROOKS, BUTLER, L DECK, C. A.

DEGENHART, K. R

DIETER, T. J. DIETERLE, S. E

FERRERA, D. W

GIACOMINI, J. J. HIETT, S. B. ISOM, J. H.

LINDSAY, D. C LONG, J. W.

LYLE, J. L. MARTINEZ, L. A NAGEL, R. E.

SHELTON, D. C. SPEARS, M. S.

WIENEIPK

TRICE, K. D.

TIME N. B WILLIAMS, J.

ZAHM, C

NYSHO

NORTH, K PARKER, A. M. RODGERS, A. D

October 10, 2003

Mr. Joe Legare Acting Assistant Manager for Environment and Stewardship U.S. Department of Energy, Rocky Flats Field Office 10808 Highway 93, Unit A Golden, CO 80403-8200

RE: Closeout Reports for Buildings 560, T452F, T891F, and T891O

Dear Mr. Legare:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the Closeout Reports for Buildings 560, T452F, T891F, and T891O, dated October 15, 2002. These are indicated to have been provided for our approval. However, as Type 1 facilities we generally receive these Closeout Reports for our information, review, and comment rather than approval. As such, we do have the following comment:

Closeout Reports should identify all removal activity and include a map of the facility identifying the structures involved, those removed, and the location of remaining infrastructure and its condition. Infrastructure includes all remaining materials and their location, and includes slabs, piers, footings, water pipes, gas lines, electrical conduits, drain lines, PWLs, sewer lines, etc. These maps are necessary for possible ER and/or future stewardship concerns. No maps have been provided for any of these facilities. The discussion provided for T891F, which had plant water and sanitary hook ups, does not specifically address the infrastructure removed or remaining. Therefore, appropriate discussion for T891F indicating the condition of remaining in-ground infrastructure, and maps for all of these facilities need to be provided.

COR. CONTROL ADMN, RECORD PATS/130

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek at (303) 692-3328.

Reviewed for Addressee Corres. Control RFP

> Steven H. Gunderson RFCA Project Coordinator

Sincerely

cc:

Ref. Ltr. #

Steve Tower, DOE

Dave Shelton, KH Karen Wiemelt, KH David Abelson, RFCLOG Tim Rehder, EPA Mike Auble, KH Steve Nesta, KH

Administrative Records Building T130G

DOE ORDER #

ADMIN RECORD

IA-A-001709